

## Domestic/Landlord Gas Safety Record

Certificate Reference 10 Granville St

Certificate No: 01

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

En	igineers De	etails					Instal	Installation Details						Client D	etails						
Trading Title		Scott Mee Plumbing Heating And Gas Services						Installation Address						Client Addres		ouses					
Address		9 Kirkstone Ave						1622	10 Granville St					Addres	90 Pa	aget St					
		Heanor							Loughborough						Loughborough						
		Derbyshire																			
		Post Code: De757uj							Post Code: LE113BN						Post Code: LE11 5DT						
Car	s Safe No:	670139 Telephone No: 07576807489						Telephone N		·				Telephone No: 01509		01509 23883	38838				
								priorie iv		Inspection Details				relephone No.							
Appliance Details						I		Τ	Inspec	tion Det	ails	T T			1 1						
	Locatio	on	Appliance Type		Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA/VIO) (VD = Visual Inspector Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)		
1	Kitche	Kitchen		bi Boiler	Main	Main	8.8	73	RS	YES	0.0009	YES	19.07 mbar	YES	NA	YES	PASS	NA	YES		
2																					
<del>                                     </del>																					
3																					
4																					
5																					
Fa	ults/Notes	:						Remedial Work Taken										Warning Notice Fixed			
1								Recharged expansion vessel.										NA			
2																					
3																					
4																					
5																					
Eme	Iergency Cont essible:	rol Valve		Yes	Gas Tightness Sati	sfactory: YES		Signatures Gas ID Number:										5369108			
	Installation F	Pipework	L		tisfactory:	Yes		Report Issued By:													
				<u></u>				Name: Scott Mee Signed:					SMee	: [Mon-10	Mon-10-Jul-2023						
Number of Appliances Tested: 1 Equipotential Bonding: Yes  NEXT INSPECTION DUE ON Wed 10 Jul 2024 Installation Page: Yes								Report Received By:						_							
OR BEFORE: Wed-10-Jul-2024 Installation Pass: Yes						Nar	me: s	Scott Mee Signed:				SNU		_ Date:	Mon-10	-Jul-2023					
CO	Alarm fitted 8	& working	g? [	YES Sr	noke alarm fitted 8	working? YES		-		This Gas Sa	fety Report w	vas created b	Gas Checker So	oftware all rights	reserved wy	ww.gaschecker.co.	uk				