

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

12 Rothesay Ave

Certificate No: 01

Engineers Details								Installation Details						Client Details								
Tra	ding Title	Scott Mee Plumbing Heating And Gas Services							allation						Client		ouses					
Address		9 Kirkstone Ave						- Add 	lress	12 Rothesay Ave					Addres	90 Pa	aget St					
		Heanor							Nottingham						Loug	Loughborough						
		Derbyshire																				
		Post Code: De757uj									Post Code: NG71PU				G71PU			I	Post Coc	le: LE11 §	5DT	
Ga	s Safe No:	670139 Telephone No: 07576807489							Telephone No:					Telephone No: 01509 2388			38					
Appliance Details										Inspec	tion Det	ails				L]				
		orano								-									ω			
	Locatio	Location		Appliance Type		Make		del	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA/VIO) WD = VWLM Inspector Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	Bathroom		Combi Boiler		Baxi		6	8.9	118	RS	YES	0.0014	YES	19.99 mbar	YES	NA	YES	PASS	NA	YES	
2																						
3																						
4																						
5																						
Fa	aults/Notes	6								Rem	emedial Work Taken									Warning Notice Fixed		
1																						
2																						
3																						
4																						
5																						
Emergency Control Valve										gnature	s											
Accessible:										Report Issued By: Gas ID Numbe							D Number	5369108				
Gas Installation Pipework Visual Inspection Satisfactory:										_	cott Mee		Signed:			SMee		Date	: Fri-28-Jul-2023			
Nu	mber of Appli	iances Te	ested:	1	Equi	potential	Bonding:	Yes	Re	eport Received By:								_				
NEXT INSPECTION DUE ON Sun-28-Jul-2024 Installation Pass: Yes							· –	cott Mee		Signed:			SMee	Sme Date		Fri-28-J	Fri-28-Jul-2023					
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES									_	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk												

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.