

Domestic/Landlord Gas Safety Record

19 Bute Ave

Certificate Reference

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate No: 01

Engineers Details							Installation Details				Client Details								
Tra	ding Title	Scott Mee Plumbing Heating And Gas Services					llation						Client	Client Parrhouses Address					
Address		9 Kirkstone Ave					ess	19 Bute	Ave					S 90 Pa	90 Paget St				
		Heanor						Nottingham						Lough	borough				
		Derbyshire																	
		Post Code: De757uj						Post Code: NG71QA						Post Code: LE11 5DT				DT	
Gas	s Safe No:	670139 Telephone No: 07576807489				Teler	Telephone No:						- Telepho	Telephone No: 01509 23883		38			
Appliance Details								Inspec	tion Det	ails									
	Locatio		Appliance Typ	e Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) (VO = Vetal Inspector ON)	bui	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	en	Combi Boiler	Main	Main	9.0	43	RS	YES	0.0005	YES	19.67 mbar	YES	NA	YES	PASS	NA	YES	
2																			
3						1													
4																			
5																			
Faults/Notes							Remedial Work Taken							Warni	Warning Notice Fixed				
1																	Training reduce rixed		
2	2						1												
3																			
4							+												
5							+												
Emergency Control Valve								atures Coo ID Number 5											
Acceptible: Yes Gas rightness Satisfactory. YES								t Issued By:								5369108			
Gas	Installation I	Pipework	Visual Inspection		Scott Mee Signed:					SNee Date:			: Wed-26	Wed-26-Jul-2023					
Number of Appliances Tested: 1 Equipotential Bonding: Yes Repo								ort Received By:							_	-			
NEXT INSPECTION DUE ON OR BEFORE: Fri-26-Jul-2024 Installation Pass: Yes						Nam		cott Mee			Signed:			Date:		Wed-26	Wed-26-Jul-2023		
СО	Alarm fitted	& working	g? YES	Smoke alarm fitted		This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk													