

## Domestic/Landlord Gas Safety Record

20 Granville St

Certificate Reference

Certificate No: 01

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Engineers Details							Installation Details						Client Details						
Trading Title		Scott Mee Plumbing Heating And Gas Services					Installation Address						Client		ouses				
Address		9 Kirkstone Ave				Addr	ess	20 Granville St				Addres	90 Pa	90 Paget St					
		Heanor						Loughborough						Lough	Loughborough				
		Derbyshire																	
		Post Code: De757uj						Post Code: LE113BN							F	Post Coc	le: LE11 5	DT	
Ga	s Safe No:	670139 Telephone No: 07576807489				Tele	lephone No:					Telephone No: 01509 23883			38				
Appliance Details						_	Inspection Details												
	Locatio	on	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) WD = Vaud Imperden Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	en	Combi Boiler	Main	Main	8.7	24	RS	YES	0.0003	YES	19.02 mbar	YES	NA	YES	PASS	NA	YES	
2																			
3																			
$\vdash$																			
4																			
5 Faults/Notes						D	1: -1 \\	.d. <b>T</b> -1							W	N - 1	. Fi		
1	auits/Notes				Remedial Work Taken  Recharged expansion vessel										Warning Notice Fixed				
$\vdash$																NA			
2																			
3																			
4																			
5																			
	ergency Cont cessible:	rol Valve	Yes		Signatures Gas ID Number:									5369108					
Gas	s Installation I	Pipework	Visual Inspection Sa		Report Issued By:  Name: Scott Mee Signed: SMee								Date: Wed-12-Jul-2023						
Nur	mber of Appli	ances Te	sted: 1	Equipotential E	Bonding: Yes		Report Received By:								_		- Jul 2020		
NEXT INSPECTION DUE ON OR BEFORE: Fri-12-Jul-2024 Installation Pass: Yes						Nan	_	Scott Mee Signe				d:	Succe Date:			Wed-12	Wed-12-Jul-2023		
	Alarm fitted	& workinç	g? YES Sr	moke alarm fitted &	working? YES		This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.												