

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

30 Johnson Rd

Certificate No: 01

Engineers Details									Installation Details Client Detail											
Trading Title		Scott Mee Plumbing Heating And Gas Services						allation						Client	1	ouses				
Address		9 Kirkstone Ave						ress	30 Johnson Rd Nottingham					Addre	90 Pa	90 Paget St				
		Heanor													Loug	nborough				
		Derbyshire							NG72BX											
		Post Code: De757uj							Post Code:							I	Post Coo	le: LE11 5	5DT	
Ga	s Safe No:	670139 Telephone No: 07576807489						ephone N	lo:						one No:	01509 2388	509 238838			
Appliance Details								Inspection Details												
						1		Ê									0		<u> </u>	
	Locatio	Location		псе Туре	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) WO = Vaual Inspector ON)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	Bathroom		bi Boiler	Main	Main	8.8	41	RS	YES	0.0005	YES	19.54 mbar	YES	NA	YES	PASS	NA	YES	
2	Kitch	Kitchen		Hob	Hob	Hob	NA	NA	FL	YES	NA	YES	19.70 mbar	YES	YES	NA	NA	NA	YES	
3			1																	
4																				
5																				
Faults/Notes								Remedial Work Taken									Warnii	Warning Notice Fixed		
1	1							Recharged expansion vessel									NA			
2	1																			
3	1																			
4																				
5																				
Accessible: Yes Cas rightness Satisfactory. YES									Gas ID Number:									5369108		
Gas	s Installation	Pipeworł	k Visual In	spection Sa	atisfactory:		Scott Mee Signed:				ed:	SMee Date			Thu-03-Aug-2023					
Number of Appliances Tested: 2 Equipotential Bonding: Yes Re									eceived By:							_		0		
NEXT INSPECTION DUE ON Sat-03-Aug-2024 Installation Pass: Yes						۰ ۱		cott Mee	,		Signed:			SAUL D		Thu-03-	Thu-03-Aug-2023			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES								-	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.