

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe
Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues
(Integrity, Construction and Lining) has been carried out.

Certificate Reference	
5 Dunlop Ave	

Certificate No: 01

Engineers Details					Instal	Installation Details						Client Details							
Tra	ding Title	Scott Mee Plumbing Heating And Gas Services					Installation Address						Client Addres		ouses				
Address		9 Kirkstone Ave					5 Dunlop Ave						Addres	90 Pa	iget St				
		Heanor					NotNottingh			am				Loughborough					
		Derbyshire																	
							Post Code: NG72BW								1	Post Cor	de: LE11 5	:DT	
		Post Code: De757uj				_	Post Code. NG726W										<u></u>	,01	
Gas Safe No:		670139 Telephone No: 07576807489			Tele	Telephone No:					Telepho	38							
Appliance Details					Inspection Details														
	Locatio	on	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAV/IO)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	om	Combi Boiler	Main	Main	8.9	34	RS	YES	0.0004	YES	20.01 mbar	YES	NA	YES	PASS	NA	YES	
2																			
$\vdash$																<u> </u>			
3																<u> </u>			
4																<u> </u>			
5																			
Faults/Notes							Rem	Remedial Work Taken								Warni	Warning Notice Fixed		
1						Recha	Recharged expansion vessel.								NA				
2	2																		
3																			
4																+			
5																+			
$\Box$						- 0	1.												
Accessible: Yes   das rightness datisfactory.   YES							Gas ID Number:									536910	5369108		
Gas Installation Pipework Visual Inspection Satisfactory:  Yes  Nat							_							Silver Date: Fri-04-Aug-2023					
Number of Appliances Tested: 1 Equipotential Bonding: Yes Report F									 Зу:		2.9.10		- Cruel		_	111104-7	g 2020		
NEXT INSPECTION DUE ON OR BEFORE: Sun-04-Aug-2024 Installation Pass: Yes						Nar	_	Scott Mee Signed:					Snu Date:			Fri-04- <i>F</i>	Fri-04-Aug-2023		
CO Alarm fitted & working?  YES  Smoke alarm fitted & working?  YES  This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.																			