

## Domestic/Landlord Gas Safety Record

59 Rothesay Ave

Certificate Reference

Certificate No: 01

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Engineers Details								Installation Details						Client Details						
Trading Title		Scott Mee Plumbing Heating And Gas Services						allation						Client		ouses				
Address		9 Kirkstone Ave						lress	59 Rothesay Ave Nottingham				Addres	90 Pa	90 Paget St					
		Heanor												Lough	Loughborough					
		Derbyshire																		
		Post Code: De757uj							Post Code: NG71PU							ſ	Post Coc	de: LE11 5	DT	
Gas	s Safe No:	670139 Telephone No: 07576807489						elephone No:					Telephone No: 01509 23883			38				
Appliance Details								Inspection Details				ails								
	Locatio	on	Appliance Type		Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) WD = Vauel Impedion Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	Kitchen		bi Boiler	Main	Main	8.9	44	RS	YES	0.0005	YES	19.45 mbar	YES	NA	YES	PASS	NA	YES	
2																				
3																				
4																1				
5																				
Faults/Notes								Pom	edial Wo	rk Takor							Warni	ag Notice	a Fixad	
1								Remedial Work Taken  Recharged expansion vessel										Warning Notice Fixed NA		
2																				
3																				
4																				
5																				
	ergency Cont	trol Valve					e i	anaturo	•											
Emergency Control Valve Accessible:  Yes  Gas Tightness Satisfactory:  YES								Signatures  Report Issued By:  Gas ID Nu							ID Number:	per: 5369108				
Gas	Installation I	Pipework	Visual Ir	nspection Sa	atisfactory:	Yes	1						d:	SNee	: Wed-26	Wed-26-Jul-2023				
Number of Appliances Tested: 1 Equipotential Bonding: Yes								ے port Re	port Received By:							_				
NEXT INSPECTION DUE ON OR BEFORE: Fri-26-Jul-2024 Installation Pass: Yes						٦	. –	cott Mee	<u>,                                      </u>		Signe	d:	SMee	Date:		Wed-26	Wed-26-Jul-2023			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES							]	This Gas Safety Report was created by Gas Checker Software all rights reserved, www.gaschecker.co.uk												