



## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference	
160 Harrington	

Certificate No: 1

Engineers Details							Inst	Installation Details						Client Details						
Trading Title GW Plumbing and Heating					tallation						Client		Houses							
Address		7 Hertford Close							dress	160 Harrington Drive				Address	90					
		Syston						Lenton					Paget Street							
		Leicester							Nottingham					Loughborough						
Post Code: LE7 2FA							Post Code: NG7 1JH							I	Post Cod	<b>le</b> : LE11 5	DT			
Gas Safe No:		944162 Telephone No: 07788379040						Telephone No:						Telephone No:						
Appliance Details										Inspection Details										
	Location		Appliance Type		Make		Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NAVIO)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Veriniation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	oliance e To Use S/NO)
								CO2	Con	Оре	8	App Insp	Flue (OF/	App (YES	Saf Con Ope	Sati (7Eg	Visu Of F Tern Sati (YES	Flue Test (PAS	App Sen (YES	App Safe (YES
1	Bathroom		Combi boiler		Main		Eco Elite 30 Combi	0.0001	0.0005	29.3 kw	34ppm	YES	RS	YES	YES	YES	YES	PASS	NO	YES
2																				
3																				
4																				
5																				
Faults/Notes							Remedial Work Taken									Warning Notice Fixed				
1																				
2																				
3																				
4																				
5																				
Emergency Control Valve Accessible:  YES  Gas Tightness Satisfactory:  YES						Signatures  Report Issued By:  Gas ID Number:									555551	5555519				
Gas Installation Pipework Visual Inspection Satisfactory:  YES  YES												med ye	Fri-12-0	Fri-12-07-2024						
Nun	nber of Appli	ances Te	sted:	1	Equip	otential I	Bonding: YES	R	eport Re	ceived E	 Зу:	<del></del>								
NEXT INSPECTION DUE ON OR BEFORE: Mon-04-08-2025 Installation Pass: YES					N	ame:	Signed:							Date:	Fri-12-0	7-2024				
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk																				