



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

17 Dunlop

Certificate No: 1

Er	ngineers De	etails							illation D	etails					Client Details						
Trading Title		GW Plumbing and Heating							allation dress						Client Address		Houses				
Address		7 Hertford Close						7		17 Dunlop Avenue					7 (44)	90					
		Syston								Lenton						Paget	Paget Street				
		Leicester						Nottingham					Loughborough								
		Post Code: LE7 2FA							Post Code: NG7 2BW						Post Code: LE11 5DT						
Gas Safe No:		944162 Telephone No: 07788379040						J Tel	ephone N	lo:					_ Telephor	ne No:					
									ор. тот. о	Inspection Details					, olopiio.						
Appliance Details								> 0	ΙÔ	n 9		lion beta									
	Locatio	Location		Appliance Type		Model		Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NAWIO) (VIO = Vieual Inspector) (VIO = VIIO Inspector) (VIO = VIIO Inspector) (VIII Inspec	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	Bathroom		Combi boiler		Eco Elite 30 C	ombi (0.0001	0.0005	29.3 kw	41ppm	YES	RS	YES	YES	YES	YES	PASS	NO	YES	
2	Kitchen		Hob		Lamona	4 Burner		NA	NA	10kw	NA	YES	FL	YES	YES	YES	NA	NA	NO	YES	
3																					
4																					
5																					
Faults/Notes									Remedial Work Taken									Warning Notice Fixed			
1																					
2	2																				
3																					
4	4																				
5																		1			
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES									Signatures Report Issued By: Gas ID Number:										5555519		
Gas Installation Pipework Visual Inspection Satisfactory:									Name: Grant Wright Signed: Date:								Fri-12-07-2024				
Nun	nber of Appli	ances Te	ested:	2	Equipoter	tial Bonding:	YES	Re	Report Received By:												
NEXT INSPECTION DUE ON OR BEFORE: Mon-04-08-2025 Installation Pass: YES								ıme:	Signed:							Date:	e: Fri-12-07-2024				
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES											This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk										