



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference	
28 Elmsthorpe	

Certificate No: 1

Engineers Details				Insta	Installation Details						Client Details							
Trading Title GW Plun		GW Plumbing and Heating				Installation Address					Client Addres	ss l	Houses					
Address		7 Hertford Close						28 Elmsthorpe Avenue					1	90				
		Syston				Lenton					Paget Street							
		Leicester						Nottingham					Loughborough					
	Post Code: LE7 2FA				Post Code: NG7 2BU					Post Code: LE11 5DT					DT			
		T GOL GOAL ELIZIA				=												
Gas Safe No: 944162 Telephone No: 07788379040		379040	Tel	Telephone No:						Telepho								
Ap	opliance De	etails							Inspec	tion Deta	ails							
	Locatio	on	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (VIO = Vieual Inspector Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Bathro	om	Combi boiler	Main	Eco Elite 30 ERP	0.0001	0.0003	29.4 kw	27ppm	YES	RS	YES	YES	YES	YES	PASS	NO	YES
2	Kitche	en	Hob	4 Burner	4 Burner	NA	NA		NA	YES	FL	YES	YES	YES	NA	NA	NO	YES
3																		
4																		
5																		
Faults/Notes				<u> </u>	Remedial Work Taken								l	Warnir	ng Notic	e Fixed		
1																		
2																		
3																		
4																		
5																		
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES						Signatures Report Issued By: Gas ID Number:								5555519				
Gas Installation Pipework Visual Inspection Satisfactory:					1						Date: Fri-1				-12-07-2024			
Nun	nber of Appli	ances Te	sted: 2	Equipotential I	Bonding: YES] Re		ceived E										
NEXT INSPECTION DUE ON OR BEFORE: Sun-03-08-2025 Installation Pass: YES				٠	ıme: [Date: Fri-12-				2-07-2024			
	Alarm fitted a	& working	g? YES Sr	noke alarm fitted &	& working? YES]	Fo	or appliances	This Gas Sa	fety Report w	as created by	y Gas Checker S d 'Appliance Sat	oftware all rights e' response is ba	reserved ww ased on a visu	vw.gaschecker.co ual check for obvio	.uk ous defects o	nly.	