



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference	
30 Johnson	

Certificate No: 1

Engineers Details									stallation Details Client Details													
Tra	ding Title	GW Plumbing and Heating							allation						Client		Parr Houses					
Address		7 Hertford Close							dress	30 Johnson Avenue					Addres	90 g	90					
		Syston								Lenton					Paget Street							
		Leicester								Nottingham						Lougl						
			Post Code: LE7 2FA							Post Code: NG7 2BX							ı	Post Cod	de: LE115	DT .		
Gas	s Safe No:	944162 Telephone No: 07788379040						Tel	Telephone No:						Telepho	one No:			$\overline{}$			
Appliance Details					Inspection Details																	
	Locatio	ion Appli		ance Type Make		,	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (VD = Vexal Impercion Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)		
1	Bathro	oom Co		nbi boiler Main		1	Eco Elite 30 Combi	0.0002	0.0010	29.9 kw	54PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES		
2	Kitchen		Hob		Lamona		4 Burner	NA	NA	10.5 kw	NA	YES	FL	YES	YES	YES	NA	NA	NO	YES		
3																						
4																						
5																						
Fa	ults/Notes				<u> </u>				Remedial Work Taken									Warning Notice Fixed				
1																						
2																						
3	3																					
4																						
5																						
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES								Signatures Report Issued By: Gas ID Number:									555551	5555519				
Gas Installation Pipework Visual Inspection Satisfactory:																Mon-22	Mon-22-07-2024					
Number of Appliances Tested: 2 Equipotential Bonding: YES Rep								Report Received By:														
NEXT INSPECTION DUE ON OR BEFORE: Sun-03-08-2025 Installation Pass: YES					1	Name: Signed: Date:								Mon-22-07-2024								
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES]			This Gas Sa	fetv Report w	as created by	v Gas Checker S	oftware all rights	reserved wy	vw.gaschecker.co.	.uk					