



## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference	
44 Bute	1

Certificate No: 1

Engineers Details					Insta	Installation Details				Client Details								
Trading Title		GW Plumbing and Heating					Installation Address						Client Address	: I	Houses			
Address		7 Hertford Close				7,50		44 Bute Avenue					71001000	90				
		Syston						Lenton						Paget	Street			
		Leicester						Nottingham					Loughborough					
		Post Code: LE7 2FA						Post Code: NG7 1QA						Post Code: LE11 5DT				DT
Gas Safe No:		944162 Telephone No: 07788379040				Tel	Telephone No:				<del></del> Telephon							
Appliance Details				Inspection Details														
	Locatio		Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NAVIO) (VD Vaual Impedien Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Bathro	om	Combi boiler	Baxi	836 Combi	0.0002	0.0018	35.6 kw	168PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES
2																		
3																		
4																		
5																		
Faults/Notes							Remedial Work Taken									Warnii	ng Notic	e Fixed
1																		
2																		
3																		
4																		
5																		
Emergency Control Valve Accessible:  YES  Gas Tightness Satisfactory:  YES							Signatures Gas ID Number: Report Issued By:									5555519		
Gas Installation Pipework Visual Inspection Satisfactory:  YES												The Die	Date:			Mon-22-07-2024		
Number of Appliances Tested: 1 Equipotential Bonding: YES Rep								ceived E	Ву:						_			
NEXT INSPECTION DUE ON OR BEFORE: Sun-20-07-2025 Installation Pass: YES				٦	me:	Signed:					Date:			Mon-22-07-2024				
CO Alarm fitted & working?  YES  Smoke alarm fitted & working?  YES  This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk  For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.																		