

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

Parrs

Certificate No: 01

Engineers Details						Install	Installation Details					Client Details								
Trading Title		Scott Mee						llation ess						Client Addre		ouses				
Address		9 Kirkstone Ave						ess	28 Chest	stnut Street				Addre	90 Pa	90 Paget Street				
		Heanor Derbyshire							Loughborough					Lough	nborough					
		Post Code: De757uj							Post Code: LE113BE							Post Code: LE115DT				
Gas Safe No:		670139 Telephone No: 07576807489						phone N						Telephone No:		01509238838				
Appliance Details							Inspection Details													
										Inspec	lion Dei	alis			1	1				
	Locatio	Location		nce Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) WD=V&MAVIO	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	Kitchen		bi Boiler	Baxi	Baxi	8.9	79	RS	YES	0.0009	YES	21.03 mbar	YES	NA	YES	PASS	NA	YES	
2																				
3																				
4																				
5																				
Faults/Notes								Remedial Work Taken								Warning Notice Fixed				
1																				
2																				
3																				
4																				
5																				
Emergency Control Valve									S						Cas			2		
Accessible: Rep								ort Iss	t Issued By: Gas ID Number:								575637	5756370		
Gas Installation Pipework Visual Inspection Satisfactory: Yes Nam									Scott Mee Signed:				ed:	SMee Date			: Thu-07-	Thu-07-Nov-2024		
								ort Re	t Received By:											
NEXT INSPECTION DUE ON Sat-18-Oct-2025 Installation Pass: Yes					ion Pass: Yes	] Nan	ne:				Signed:			SMu Date:		Thu-07-	Thu-07-Nov-2024			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES							]	-	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.