

## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

34 Teversal Avenue

Certificate No: 1

| Engineers Details   |                          |                                  |              |         |                     |                     |  | Installation Details                      |   |                  |   |                        |   | Client E  |  |   |  |                                      |                                      |  |  |  |  |
|---|--------------------------|----------------------------------|--------------|---------|---------------------|---------------------|--|---|---|------------------|---|------------------------|---|---|--|---|--|--------------------------------------|--------------------------------------|--|--|--|--|
| Trading Title   |                          | GW Plumbing and Heating          |              |         |                     |                     |  | tallation                                 |   |                  |   |                        |   | Client  |  | Houses  |  |                                      |                                      |  |  |  |  |
| Address   |                          | 7 Hertford Close                 |              |         |                     |                     |  | dress                                     | 37 Teversal Avenue                          |                  |   |                        |   | Addres  | 90   | 90  |  |                                      |                                      |  |  |  |  |
|   |                          | Syston                           |              |         |                     |                     |  |   | Lenton                                      |                  |   |                        |   |   | Page   | Paget Street  |  |                                      |                                      |  |  |  |  |
|   |                          | Leicester                        |              |         |                     |                     |  |   | Nottingham                                  |                  |   |                        |   |   | Loughborough   |   |  |                                      |                                      |  |  |  |  |
|   |                          | Post Code: LE7 2FA               |              |         |                     |                     |  |   | Post Code: NG7 1PX                          |                  |   |                        | 7 1PX   |   |  |   | Post Coo                                   | <b>de:</b> LE115                     | 5DT                                  |  |  |  |  |
| Gas Safe No:  |                          | 944162 Telephone No: 07788379040 |              |         |                     |                     |  | Telephone No:                             |   |                  |   |                        | Telephone No:   |   |  |   |  |                                      |                                      |  |  |  |  |
| A   | opliance D               | etails                           |              |         |                     |                     | ]  |   |   | Inspec           | tion Det  | ails                   |   |   |  | L   |  |                                      |                                      |  |  |  |  |
|   | Locatio                  | Location                         |              | се Туре | Make Model          |                     | Combustion LOW<br>(C02% or CO/CO2 ratio) | Combustion HIGH<br>(C02% or CO/CO2 ratio) | Heat Input (KW)<br>or<br>Operating Pressure | CO Reading (ppm) | Appliance<br>Inspected<br>(YES/NO/NAVIO)<br>(VD = Vead Imposter Only) | FlueType<br>(OF/RS/FL) | Landlords<br>Appliance<br>(YES/NO/NA)   | Safety Device(s)<br>Correct<br>Operation<br>(YES/NO/NA) | Ventilation<br>Provision<br>Satisfactory<br>(YES/NO) | Visual Condition<br>Of Flue and<br>Termination<br>Satisfactory<br>(YES/NO/NA) | Flue Performance<br>Test<br>(PASS/FAIL/NA) | Appliance<br>Serviced<br>(YES/NO/NA) | Appliance<br>Safe To Use<br>(YES/NO) |  |  |  |  |
| 1   | Bathroom                 |                                  | Combi boiler |         | Main                | Eco Elite 30 ERP    | 0.0001                                   | 0.0006                                    | 29.3 kw                                     | 50PPM            | YES   | RS                     | YES   | YES   | NA   | YES   | PASS                                       | NO                                   | YES                                  |  |  |  |  |
| 2   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 3   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 4   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 5   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| Faults/Notes  |                          |                                  |              |         |                     | Remedial Work Taken |  |   |   |                  |   |                        |   |   | Warning Notice Fixed                                 |   |  |                                      |                                      |  |  |  |  |
| 1   | 1                        |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 2   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 3   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 4   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| 5   |                          |                                  |              |         |                     |                     |  |   |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
|   | ergency Cont<br>essible: | trol Valve                       | Э            | YES     | Gas Tightness Sat   |                     | Signatures Gas ID Number:                |   |   |                  |   |                        |   |   |  |   | 5555519                                    |                                      |                                      |  |  |  |  |
| Accessible: YES Gas Tightness Satisfactory: YES   Gas Installation Pipework Visual Inspection Satisfactory: YES |                          |                                  |              |         |                     |                     |  | Report Issued By:                         |   |                  |   |                        |   |   |  |   |  |                                      |                                      |  |  |  |  |
| Number of Appliances Tested: 1 Equipotential Bonding: YES   |                          |                                  |              |         |                     |                     |  |   | Grant Wright Signed: Date                   |                  |   |                        |   |   |  | Mon-22-07-2024  |  |                                      |                                      |  |  |  |  |
|   |                          |                                  |              |         |                     | 7                   | · –                                      | Received By:                              |   |                  |   |                        |   |   | Mon 22   | 07 2024   |  |                                      |                                      |  |  |  |  |
| OR BEFORE:  |                          |                                  |              |         |                     | ame:                | Signed: Date:                            |   |   |                  |   |                        | Mon-22-07-2024  |   |  |   |  |                                      |                                      |  |  |  |  |
| CO  | Alarm fitted             | & workin                         | g?           | YES Sr  | moke alarm fitted & | & working? YES      |  | -   |   | This Gas Sa      | fety Report w   | as created by          | This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk |   |  |   |  |                                      |                                      |  |  |  |  |

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.