



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

Certificate Reference

38 Teversal Avenue

Certificate No: 1

Engineers Details								allation Details Client Details												
Trading Title GW Plumbing and Heating			ting			ation						Client	Client Parr Houses							
Address	Ē	7 Hertford Close					☐ Addres	SS	38 Teversal Avenue						ss 90					
		Syston						Lenton							Paget	Paget Street				
		Leicester							Nottingham					Loughborough						
		Post Code: LE7 2FA								Post Code: NG7 1PX						Post Code: LE11 5DT				
	[] Tolophono No.												
Gas Safe No: 944162 Telephone No: 07788379040						leiepr	Telephone No:						Telepho							
Appliance Details										Inspec	tion Det	ails				,				
	Location	n	Appliand	ce Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NAVIO) WD = Veuel Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1																				
2																				
\vdash																				
3																				
4																				
5											<u> </u>									
Faults/	Notes						Remedial Work Taken									Warning Notice Fixed				
1																				
2																				
3																				
4																				
5																				
Emergend Accessible		rol Valve	Y	ES (Gas Tightness Sat		Signatures Report Issued By: Gas ID Number:										5555519			
Gas Insta	llation P	Pipework	Visual Ins	pection Sa	tisfactory:	YES	•										Mon-22-07-2024			
Number o	of Applia	ances Tes	sted: 0		Equipotential I	Bonding: YES		Report Received By:												
NEXT INSPECTION DUE ON OR BEFORE: Mon-04-08-2025 Installation Pass: YES					Name								Mon-22-07-2024							
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES										This Gas Sa	fety Report w	as created b	y Gas Checker	Software all rights	s reserved wy	vw.gaschecker.co	.uk			