

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

57 Teversal Avenue

Certificate No: 1

Engineers Details								Installation Details					Client Details							
Trading Title		GW Plumbing and Heating						tallation						Client		Houses				
Address		7 Hertford Close						dress	57 Teversal Avenue				Address	90	90 Paget Street					
		Syston							Lenton					Page						
		Leicester							Nottingham						Loughborough					
		Post Code: LE7 2FA							Post Code: NG7 1PY				67 1PY				Post Coo	de: LE115	DT	
Ga	s Safe No:	944162 Telephone No: 07788379040					Te	lephone N	ne No:					Telephone No:						
Appliance Details							Inspection Details													
	Locatio	Location		се Туре	Make	Model	Combustion LOW (C02% or CO/C02 ratio)	Combustion HIGH (C02% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YESNO/NAVIO) (VICS-Veux Inspected Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bathro	Bathroom		oi boiler	Main	Main Eco Elite 30 Combi		0.0006	29.2 kw	50PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES	
2																				
3																				
4																				
5																				
Faults/Notes								Remedial Work Taken									Warni	Warning Notice Fixed		
1																				
2	1																			
3																				
4	+																			
5																				
	L ergency Cont	rol Valve	Это С	YES	Gas Tightness Sat	isfactory: YES	S	Signatures Gas ID Number:									555551	5555519		
Cas Installation Pinework Visual Inspection Satisfactory:									Report Issued By:											
									Grant Wright Signed: Date						Mon-22-07-2024					
	nber of Appli			1	Equipotential	Bonding: YES	J R€	Report Received By:												
NEXT INSPECTION DUE ON Thu-31-07-2025 Installation Pass: YES] Na	ame:	Signed:					Date:	Mon-22	-07-2024					
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES								_	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.