

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

6 Teversal Avenue

Certificate No: 1

Engineers Details									Insta	Installation Details						Client Details						
Trading Title		GW Plumbing and Heating							Installation Address						Client Addres		Houses					
Address		7 Hertford Close								iress	6 Teversal Avenue					Addres	90	90				
		Syston								Lenton					Paget Street							
		Leicester								Nottingham					Loughborough							
		Post Code: LE7 2FA									Post Code: NG7 1PX							I	Post Cod	de: LE115	DT	
Gas Safe No:		944162 Telephone No: 07788379040							Telephone No:							Telephone No:						
_	ppliance De												Inspection Details									
Γ	Locatio		Appliance Type		Make		Model		Combustion LOW (co2% or co/co2 ratio)	Combustion HIGH (C02% or CO/C02 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) 003 = Yaual Propender Off)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
									Con (CO2	(CO2	Hea	00 C	App Insp (YES/	Flue (OF/	Lan App (YES	Saf Con Ope	Ven Prov Sati	Vist Tern Sati	Flue Test (PAS	App Sen YES	App Safe (YES	
1	Bathroom		Combi boiler		Main		Eco Elite 30 Combi		0.0001	0.0006	29.6 kw	54PPM	YES	RS	YES	YES	NA	YES	PASS	NO	YES	
2																						
3																						
4																						
5																						
Faults/Notes								Remedial Work Taken									Warning Notice Fixed					
1	i l																					
2	2																					
3																						
4																						
5	5																					
Assessible: YES Cas rightness Satisfactory: YES										gnatures Gas ID Number:									5555519			
Cas Installation Binowork Visual Inspection Satisfactory:										·	ort Issued By: ne: Grant Wright Signed: Dat						Date:	: Mon-22-07-2024				
Number of Appliances Tested: 1 Equipotential Bonding: YES									Re	Report Received By:							L]			
	XT INSPECTI BEFORE:	ON DUE ON Sun-03-		Sun-03-08	08-2025 Installation P		ion Pass:	YES	1	Name:		,		Signe	Signed:				ate: Mon-22-07-2024			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES									5	This Gas Safety Report was created by Gas Checker Software all rights reserved, www.gaschecker.co.uk												

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.